

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1









Fig. 7




Fig. 8




Fig. 9A

FIG. 9B




Fig. 10




Fig. 11




Fig. 12




Fig. 13A




Fig. 14




Fig. 15




Fig. 17




Fig. 16




FIG. 18




FIG. 19





FIG. 20

Fig. 21







FIG. 22

FIG. 23







FIG. 24

FIG. 25







FIG. 26

FIG. 34






FIG. 27




FIG. 28




Fig. 1B




Fig. 1A




Fig. 1D














Fig. 1C














Fig. 1P




Fig. 1O




Fig. 18




Fig. 19

Fig. 11






Fig. 15



A perspective sketch of a rectangular box, possibly a container or a piece of furniture. The box is shown from a three-quarter view, revealing its top, front, and right side. The interior of the box is filled with a dense, dark, cross-hatched pattern, suggesting a solid or heavily textured material. The exterior surfaces are outlined with simple lines, and some areas are filled with diagonal hatching. An arrow points from the left side of the frame towards the front-left corner of the box. The entire sketch is enclosed within a rectangular border.

Fig. 1 W.




Fig. 12






Fig. 14






Fig. 1A3




Fig. 1AE




Fig. 1AD

FIG. 29






FIG. 29A








Fig. 34




FIG. 32





FIG. 35

FIG. 36



This diagram shows a cross-sectional view of a mechanical assembly. Key components and their reference numerals include: 264 (a vertical wall or plate), 397 (a small rectangular component), 228 (a horizontal wall), 304 (a vertical wall), 230 (a horizontal wall), 302 (a vertical wall), 226 (a horizontal wall), 308 (a vertical wall), 280 (a horizontal wall), 322 (a horizontal wall), 318 (a horizontal wall), 310 (a horizontal wall), 306 (a horizontal wall), 320 (a horizontal wall), 316 (a horizontal wall), 301 (a vertical wall), 324 (a horizontal wall), and 300 (a horizontal wall). The assembly appears to be a housing or a support structure for a component, with various walls and openings.

FIG. 38

